

U S A S  
X8.1-1968  
Approved March 12, 1968  
USA STANDARDS INSTITUTE

EIA RS-267-A

# EIA STANDARD

*Axis and Motion Nomenclature  
for  
Numerically Controlled  
Machines*

**RS-267-A**  
*(Revision of RS-267)*



*June 1967*

*Engineering Department*  
**ELECTRONIC INDUSTRIES ASSOCIATION**

## NOTICE

EIA engineering standards are designed to serve the public interest through eliminating misunderstandings between manufacturers and purchasers, facilitating interchangeability and improvement of products, and assisting the purchaser in selecting and obtaining with minimum delay the proper product for his particular need. Existence of such standards shall not in any respect preclude any member or non-member of EIA from manufacturing or selling products not conforming to such standards, nor shall the existence of such standards preclude their voluntary use by those other than EIA members whether the standard is to be used either domestically or internationally.

Recommended standards are adopted by EIA without regard to whether or not their adoption may involve patents on articles, materials, or processes. By such action, EIA does not assume any liability to any patent owner, nor does it assume any obligation whatever to parties adopting the recommended standards.

Published by

# **ELECTRONIC INDUSTRIES ASSOCIATION**

**Engineering Department**

**2001 Eye Street, N. W., Washington, D. C. 20006**

---

© Electronic Industries Association 1967

All rights reserved

**Price \$4.00**

Printed in U.S.A.

# AXIS AND MOTION NOMENCLATURE FOR NUMERICALLY CONTROLLED MACHINES

*(From EIA Standard RS-267 and Standards Proposal No. 916, formulated under the cognizance of EIA Engineering Committee TR-31 on Numerical Control Systems and Equipment.)*

## 1. SCOPE

This standard for axis and motion nomenclature for numerically controlled machines is intended to simplify programming, to simplify the training of programmers, and to facilitate the interchangeability of control tapes.

- 1.1 This standard applies to all numerically controlled machines.
- 1.2 Definitions of terms used in this standard are in accordance with EIA Automation Bulletin 3B, "Glossary of Terms for Numerically Controlled Machines", February, 1965, or latest revision thereof.
- 1.3 Revisions to these standards will be proposed as technical progress warrants.

## 2. THE STANDARD COORDINATE SYSTEM

- 2.1 The Standard coordinate system gives the coordinates of a moving tool (or draftsman's pencil) with respect to a stationary workpiece. (See Figures 1A and 1B.)
- 2.2 It shall be used for all numerical control programming, machine fixturing, and machine loading.
- 2.3 It shall be designated by unprimed letters such as x, y, and z. (See paragraph 10.)

## 3. THE Z AXIS OF MOTION

3.1 The z axis of motion is parallel to the principal spindle of the machine. If there are several spindles, one shall be selected as the principal one. If there is no spindle the z axis is perpendicular to the work holding surface. If the principal spindle can be swiveled or gimballed the z axis is parallel to the spindle axis when the spindle is in its 0 position. The preferred 0 position is with the spindle perpendicular to the work holding surface.

3.1.1 On such equipment as milling, boring, drilling, and tapping machines, the spindle is the tool rotating means.

3.1.2 On such equipment as lathes, grinders, and other machines which generate a surface of revolution, the spindle is the work rotating means.

3.2 Positive z (w and r, see paragraph 8) is in the direction from the workholding means toward the tool-holding means. Positive z motion increases the distance between the work and the tool. (See paragraph 10.)

## 4. THE X AXIS OF MOTION

- 4.1 The x axis of motion is horizontal and parallel to the workholding surface.
- 4.2 If z is horizontal, positive x is to the right looking from the spindle toward the workpiece.
- 4.3 If the z axis is vertical, when looking from the spindle toward its supporting column(s) the positive x axis is to the right on single column machines or forward on dual column or gantry machines.
- 4.4 On machines generating a surface of revolution, such as lathes, x, u, and p motions shall be radial, and normally the positive direction of motion shall be away from the center of revolution. Where the linear motion can cross the centerline of rotation, positive motion shall be in the direction of maximum displacement from the center of rotation.

## 5. THE Y AXIS OF MOTION

5.1 The y axis of motion is perpendicular to both x and z.

5.2 Positive y is in the direction to make a right-handed set of coordinates; i.e., +x rotated into +y advances a right-handed screw in the +z direction.

## 6. ROTARY MOTIONS, A, B, AND C

6.1 a, b, and c are angles defining rotary motions around the axes parallel to x, y, and z respectively.

6.2 Positive a, b, and c are in the directions to advance a right-handed screw in the +x, +y, and +z directions respectively.

## 7. THE ORIGIN OF THE STANDARD COORDINATE SYSTEM

7.1 The location of the origin ( $x = 0$ ,  $y = 0$ ,  $z = 0$ ) of the standard coordinate system and/or the angular origins ( $a = 0$ ,  $b = 0$ ,  $c = 0$ ) may be fixed or adjustable.

## 8. ADDITIONAL AXES

8.1 If in addition to the primary linear slide motions, x, y, or z, there exists secondary slide motions parallel to these, they shall be designated u, v, and w respectively. If tertiary motions exist, they shall be designated p, q, and r respectively. If linear motions exist, which are not or may not be parallel to x, y, or z, they may be designated u, v, w, p, q, or r, as is most convenient. If there are more than three (3) sets of parallel motions, unused letter addresses may be used in alphabetical order.

8.2 If in addition to the primary rotary motions a, b, or c, there exist secondary rotary motions, either parallel to a, b, or c or compound or gimbaled to a, b, or c, they shall be designated d or e.

8.3 The primary linear motions are those nearest the principal spindle; the secondary motions are those next nearest; the tertiary are the farthest. For example, the carriage on a turret lathe is z, while the saddle, being farther from the spindle, is w.

8.4 It is recommended that axis selection be based upon the most complex version of a machine. Simpler versions of such a machine derived by a deletion of assigned axes need not alter the designation or positive directions of the remaining axes.

## 9. DIRECTION OF SPINDLE ROTATION

9.1 Clockwise spindle rotation is in the direction to advance a right-handed screw into the workpiece.

## 10. REVERSED DIRECTIONS FOR MOVING WORKPIECES

10.1 If a machine element moves the workpiece instead of the tool, it must respond to the tape in the opposite direction from that defined above for moving the tool. In illustrating various machine tools, an arrow with a primed letter, such as +x', is the direction of motion of a moving workpiece for a command calling for positive motion; while an arrow with an unprimed letter, such as +x, is the direction of motion for the same positive command of the tool with respect to the workpiece. (The programmer, fixturing set-up man, and machine loader should think exclusively in terms of the unprimed directions. Only the machine builder need consider the primed directions.)

## 11. SCHEMATIC DRAWINGS OF NUMERICALLY CONTROLLED MACHINES

11.1 Schematic drawings of typical machines interpreting this standard are shown on the following pages.

11.1.1 The schematic drawings indicate by letters and arrows the motions normally numerically controlled. On machines similar to those shown, but with more or less numerically controlled motions, Section 8 shall apply.




FIG. 1A






FIG. 1B  
RIGHT HAND COORDINATE SYSTEM






FIG. 4  
RIGHT ANGLE LATHE




FIG.5  
VERTICAL TURRET LATHE  
VERTICAL BORING MILL





FIG. 6  
HORIZONTAL KNEE MILL






FIG. 7  
VERTICAL KNEE MILL  
DRILLING MACHINE  
JIG BORER




FIG. 8  
HORIZONTAL BORING MILL




FIG.9  
PROFILING AND CONTOUR MILL





FIG. 10  
GANTRY PROFILER




FIG. II  
BRIDGE PROFILER




FIG. 12  
PROFILE AND CONTOUR MILL — MOVING TABLE  
AND 5 AXES.




FIG. 13  
PROFILE AND CONTOUR  
MILL HORIZ. SPINDLE AND 5 AXES




FIG. 14  
PROFILE AND CONTOUR MILL  
TILTING HEAD AND 5 AXES




FIG. 15  
PROFILE AND CONTOUR MILL—TILTING TABLE  
AND 5 AXES






FIG. 16  
RIGHT HAND TUBE BENDER




FIG. 17  
CYLINDRICAL GRINDER




FIG. 18  
TOOL AND CUTTER GRINDER




FIG. 19

FIVE PRINCIPAL PROBE  
ATTITUDES AND ASSOCIATED  
AXES. NUMERICALLY  
CONTROLLED MEASURING  
INSPECTION MACHINE.




FIG. 20  
INSPECTION MACHINE




FIG. 21  
INTERNAL-EXTERNAL INSPECTION MACHINE




FIG 22  
VERTICAL FILAMENT WINDING MACHINE




FIG. 23

HORIZONTAL FILAMENT WINDING MACHINE






FIG. 24  
WELDING MACHINE




FIG. 25  
FLAME CUTTING MACHINE




FIG. 26  
TURRET PUNCH PRESS




FIG. 27  
DRAFTING MACHINE

