



**HEWLETT-PACKARD COMPANY  
LOGIC SYSTEMS DIVISION**

**HP 64000  
Logic Development  
System**

**SYSTEM RELEASE BULLETIN**

Part Number: **5958-6019**  
**E0888**

Printed: **AUGUST 1988**



\*\*\*\*\*

**HP STARS II**

**64000 SOFTWARE RELEASE BULLETIN**

**UPDATE 88.08A**

**AUGUST, 1988**

**This document supersedes all previously dated SSBs.**

**HEWLETT  
PACKARD**

\*\*\*\*\*

\*\*\*\*\*

NOTICE

The information contained in this document is subject to change without notice.

HEWLETT-PACKARD MAKES NO WARRANTY OF ANY KIND WITH REGARD TO THIS MATERIAL, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. Hewlett-Packard shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance or use of this material.

Hewlett-Packard assumes no responsibility for the use or reliability of its software on equipment that is not furnished by Hewlett-Packard.

This document contains proprietary information which is protected by copyright. All rights are reserved. No part of this document may be photocopied, reproduced or translated to another language without the prior written consent of Hewlett-Packard Company.

\*\*\*\*\*

READER COMMENT SHEET

STARS II SRB (STARS B)

Issue \_\_\_\_\_ DATE \_\_\_\_/\_\_\_\_/\_\_\_\_

We welcome your evaluation of this bulletin. Your comments and suggestions help us to improve our publications. Please use additional pages if necessary.

Is this bulletin technically accurate? Yes [ ] No [ ] (If no, explain under Comments, below.)

Are the concepts and wording easy to understand? Yes [ ] No [ ] (If no, explain under Comments, below.)

Is the format of this bulletin convenient in size, arrangement and readability? Yes [ ] No [ ] (If no, explain or suggest improvements under Comments, below.)

Comments:

\*\*\*\*\*

Date: \_\_\_\_\_

FROM:

Name \_\_\_\_\_

Company \_\_\_\_\_

Address \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_


STARS B  
Printed in U.S.A.

FOLD

FOLD



NO POSTAGE  
NECESSARY  
IF MAILED  
IN THE  
UNITED STATES



# BUSINESS REPLY MAIL

FIRST CLASS PERMIT NO. 1303 COLORADO SPRINGS, CO.



POSTAGE WILL BE PAID BY ADDRESSEE

STARS Administration  
Hewlett-Packard Company  
Logic Systems Division  
P.O. BOX 617  
Colorado Springs, Colorado 80901-0617

FOLD

FOLD

## P R E F A C E

This Software Release Bulletin documents all fixes and enhancements that are incorporated in the new release identified on the cover page. The SRB is provided as a benefit of Hewlett-Packard's Account Management Support, Response Center Support, and Software Materials Subscription.

Of the five sections contained in the SRB (not including the PREFACE), only the last section which contains the detailed reports has page numbers. These are referenced by the product, report number and keyword indexes in order to direct the user to a particular area or to an individual detailed report. The five sections are described below.

### SOFTWARE RELEASE CONTENTS

This section lists the product names, numbers and update/fix levels of all products contained in this release. Products that have changed, or are new are denoted with an asterisk preceding the product name.

### PRODUCT INDEX

Each unique product name/number has an entry listing the page number where the detailed report for that product begins.

### REPORT NUMBER INDEX

This index is a sequential list of the individual report numbers with the corresponding page number where the report can be found.

### KEYWORD INDEX

This index is sorted by product name, keyword, product number (including the update/fix level) and by report number in that order. In addition to the sort items, each entry has a brief description (one line) and the page number where the detailed report can be found. Note that a given report can be listed more than once in this section if it has more than one keyword assigned to it.

### DETAILED REPORTS

Each report contains all the available information relevant to the problem being corrected or the enhancement being implemented.





## Software release contents

Product name	Product number	uu.ff
*6301V EMULATION	300 64206S004	01.10
*68000 12MHZ EMUL	DOS 64742S006	01.01
*68000 ASSEMB	DOS 64845S006	02.11
*68010 16MHZ EMUL	DOS 64745S006	01.01
*68020 EMUL	300 64410S004	02.10
*80186 EMUL	DOS 64764S006	01.01
*80188 EMUL	DOS 64765S006	01.01
*8086/8 ASSEMB	DOS 64853S006	02.71
*HP TEAMWORK	300 64711S004	02.20
*NETWORK TRANSFER	500 64888S001	01.20
*STATE ANALYZER	300 64620S004	01.30
*USER DEF ASSEMB	DOS 64851S006	02.15
*UTILITIES PKG	300 64888S003	01.50
*UTILITIES PKG	300 64888S004	01.20
*Z80 EMUL	DOS 64753S006	01.01
*Z80 ASSEMB	DOS 64842S006	01.91

Product index

Product name	Product number	Page
68000 12MHZ EMUL DOS	64742S006	1
68010 16MHZ EMUL DOS	64745S006	2
68020 EMUL 300	64410S004	3
80186 EMUL DOS	64764S006	7
80188 EMUL DOS	64765S006	8
HP TEAMWORK 300	64711S004	9
STATE ANALYZER 300	64620S004	12
UTILITIES PKG 300	64888S004	13

Report number index

Report #	page	Report #	page	Report #	page	Report #	page
5000185447	13	D200076505	9	D200082487	12	D200086827	5
5000196048	10	D200076521	9	D200086769	3	D200087528	12
5000259838	13	D200076687	12	D200086777	4	D200087627	2
5000272526	1	D200076968	9	D200086785	4	D200087650	7
5000283622	3	D200076992	11	D200086793	4	D200089821	8
D200067371	10	D200078717	10	D200086819	5	D200090530	6
D200070060	9	D200082388	12				

Keyword index

- -8

Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64742S006	00.01 Address Specifiers that include "don't care" characters may fail.	5000272526	1

- -8

Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64745S006	00.00 Enhancement to add the M68010 processor registers	D200087627	2

- -8

Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64410S004	02.00 Code disp. with trace not right if code changed w/o ending emul. session	5000283622	3
	64410S004	02.00 Shared contexts are not shown as such in "copy trace_spec" output.	D200086769	3
	64410S004	02.00 "display trace find..." may not work if the status displayed is absolute	D200086777	4
	64410S004	02.00 Session may abort if fpu disabled in config while displaying fpu regs.	D200086785	4
	64410S004	02.00 Erroneous trace data may be shown with "at_execution run" command.	D200086793	4
	64410S004	02.00 Conflicts may exist between simulated interrupts and SW breakpoints.	D200086819	5
	64410S004	02.00 Long trace sequence name (gt 8 characters) is not flagged properly.	D200086827	5
	64410S004	02.00 bbaunload causes memory growth problems in emulators	D200090530	6

- -0

Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64764S006	00.01 Request for Register interface changes.	D200087650	7

- -0

Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64765S006	00.01 Invalid expressions can corrupt PC memory	D200089821	8

- -P

Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64711S004	01.00 Better use of laser printers.	5000196048	10
	64711S004	01.00 Need ability to import and export notes to and from HP-UX environment.	D200067371	10
	64711S004	01.00 Won't open Data Flow Diagram	D200070060	9
	64711S004	01.00 I/O timing loops are machine dependent. 350 runs much faster than 320.	D200076505	9
	64711S004	01.00 Title changes do not 'filter down' to lower levels.	D200076968	9
	64711S004	01.00 Wrong date displayed by load twk.	D200076992	11
	64711S004	01.00 FILES MISSING WHEN 64702 IS INSTALLED WITHOUT THE 64711 FILESET	D200078717	10
CUSTOMIZE	64711S004	01.00 Should keep the manual pages if /usr/man/man1 doesn't exist.	D200076521	9

- -T

Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64620S004	01.10 State Pv causes cardcage IMB to latch.	D200076687	12
	64620S004	01.10 Processes sometimes left running after parent has stopped.	D200082388	12
	64620S004	01.10 Display symbol shows "symb not found" when showing sym within process.	D200082487	12
	64620S004	01.10 State does not yet support the system II "set" command	D200087528	12

Keyword index

- -T

Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64888S004	01.10 Xlate cannot convert the file with address 0FFFFH	5000259838	13
ENHANCEMENT	64888S004	01.00 Desire ability to control the length of S-Records output from 64888.	5000185447	13



SRB detail reports as of 07/11/88

Page: 1

Number: 5000272526 Product: 68000 12MHZ EMUL DOS 64742S006 00.01

One-line description:

Address Specifiers that include "don't care" characters may fail.

Problem:

Address specifiers that include "don't care" characters may fail to work properly. Example:

When specifying trigger or storage addresses:

9XXXXXH - captures or triggers on addresses outside 90000H-9FFFFFFH  
90XXXXH - captures or triggers on addresses outside 90000H-90FFFFFFH  
900XXXXH - works as expected

Temporary solution:

Use the Terminal interface to specify the trace and execute the trace.

Signed off 07/11/88 in release A01.01

---

SRB detail reports as of 07/11/88

Page: 2

Number: D200087627 Product: 68010 16MHZ EMUL DOS 64745S006 00.00

One-line description:

Enhancement to add the M68010 processor registers

Enhancement text:

and the m68010 programmatics. The register additions were vbr, sfc and dfc.

Signed off 07/11/88 in release A01.01

---

Number: 5000283622 Product: 68020 EMUL 300 64410S004 02.00

## One-line description:

Code disp. with trace not right if code changed w/o ending emul. session

## Problem:

Source lines displayed with a trace may not be correct if the code is changed without ending out of the emulation session. For example, a user running is windows does a display trace source on, and sees a statement: i = 1; in the trace along with the MOVE.L #1,D0 that accompanies that source line. The user then moves to another window, changes the source line to i = 2;, recompiles, relinks, and runs edbuild. The user then moves back to the emulation window, reloads the file, and reruns the code and the trace. The trace shows MOVE.L #2,D0 as expected, BUT shows i = 1; as the source line.

End out of emulation, and reenter before loading the new program Source lines displayed with a trace may not be correct if the code is changed without ending out of the emulation session. For example, a user running is windows does a display trace source on, and sees a statement: i = 1; in the trace along with the MOVE.L #1,D0 that accompanies that source line. The user then moves to another window, changes the source line to i = 2;, recompiles, relinks, and runs edbuild. The user then moves back to the emulation window, reloads the file, and reruns the code and the trace. The trace shows MOVE.L #2,D0 as expected, BUT shows i = 1; as the source line.

## Temporary solution:

End out of emulation, and reenter before loading the new program or executing the trace.

Signed off 07/11/88 in release A02.10

Number: D200086769 Product: 68020 EMUL 300 64410S004 02.00

## One-line description:

Shared contexts are not shown as such in "copy trace\_spec" output.

## Problem:

Shared contexts are not shown as explicitly shared in the output of the copy trace\_specification... command. Instead, the context spec is repeated. E. g.

```
T_CONTEXT enable after a= 4000h
...
S_CONTEXT enable after a= 4000h
```

instead of the displayed version:

```
T_CONTEXT enable after a= 4000h
...
S_CONTEXT T_CONTEXT
```

Signed off 07/11/88 in release A02.10

Number: D200086777 Product: 68020 EMUL 300 64410S004 02.00

## One-line description:

"display trace find..." may not work if the status displayed is absolute

## Problem:

The "display trace find ..." command will fail to locate any pattern if the trace display currently shows status in absolute form (binary or hex). There is no problem, however, when source display is also on.

## Temporary solution:

Two Solutions exist:

```
-1-
Do a "display trace mnemonic ..."
or "display trace status mnemonic ..."
before the find command, or
-2-
simply enable a source display with
"display trace source on".
```

Signed off 07/11/88 in release A02.10

Number: D200086785 Product: 68020 EMUL 300 64410S004 02.00

## One-line description:

Session may abort if fpu disabled in config while displaying fpu regs.

## Problem:

When fpu registers are being displayed repetitively, and then configuration is modified and the internal fpu is disabled, the emulation session will automatically "end release" and dump core.

## Temporary solution:

Before modifying configuration to disable the fpu, issue a display command for something other than registers.

Signed off 07/11/88 in release A02.10

Number: D200086793 Product: 68020 EMUL 300 64410S004 02.00

## One-line description:

Erroneous trace data may be shown with "at\_execution run" command.

## Problem:

If no traces have been taken in the current emulation session, the commands

```
at_execution run ...
execute
```

will cause erroneous trace data to be shown. This will not occur if any traces have been taken.

Display of false data will also occur with the following commands:



```

at_execution run ...
at_execution trace ...
load_trace_specification ... (should cancel pending at_exec trace)
end (locked or to measurement_system or another module]
(resume)
execute (should cause run only)

```

Taking a trace after the load and before the "end" will prevent this.

Temporary solution:

Workarounds are described in the problem text.

Signed off 07/11/88 in release A02.10

---

Number: D200086819 Product: 68020 EMUL 300 64410S004 02.00

One-line description:

Conflicts may exist between simulated interrupts and SW breakpoints.

Problem:

Execution of software breakpoints may not be recognized by the emulator software if simulated interrupts are also being used. This occurs when the breakpoint is hit at the same time the emulator software is trying to break to the monitor to initiate a simulated interrupt. Upon completion of the simulated interrupt, the monitor will return to the users code, completely ignoring the breakpoint.

If possible, simulated interrupts should be disabled during use of breakpoints by clearing the simulated interrupt control address either from the softkeys (using modify memory) or in the user code.

Temporary solution:

If possible, simulated interrupts should be disabled during use of breakpoints by clearing the simulated interrupt control address either from the softkeys (using modify memory) or in the user code.

Signed off 07/11/88 in release A02.10

---

Number: D200086827 Product: 68020 EMUL 300 64410S004 02.00

One-line description:

Long trace sequence name (gt 8 characters) is not flagged properly.

Problem:

Names used in analysis sequence specifications are limited to eight characters in length. Longer names are automatically truncated by the software with no warning to the user. This might cause confusion if the user recalls and modifies a command on the command line since the software will not recognize the long name in a subsequent "modify" command.

Temporary solution:

Only names of 8 or less characters should be used in the sequencer.

Signed off 07/11/88 in release A02.10

Number: D200090530 Product: 68020 EMUL 300 64410S004 02.00

One-line description:

bbaunload causes memory growth problems in emulators

Problem:

Detailed Listing for Defect Number LSDqf03808

Text:

bbaunload causes memory growth problems in emulators

.submitter

The bbaunload library (/lsd/p2/cmd/bba/prod/unload) allocates memory and never frees it.

Bruce E

FIXED:

The new library fixes these problems as well as making the whole unload process much faster. It is fixed as of 03June88.

Signed off 07/11/88 in release A02.10

Number: D200087650 Product: 80186 EMUL DOS 64764S006 00.01

One-line description:  
Request for Register interface changes.

Problem:  
Register function interface ENHANCEMENTS:

1. Changed the size of the register number and class number from a u\_int8 to a u\_int16.
2. Changed the dataarray from a u\_int32 \* to an intrn \*.
3. Added the register attributes: regtype, intntype, and intnsize and removed the attributes type, and size.
4. Added the pcaobj element to the readregclstruct structure.

Signed off 07/11/88 in release A01.01

---

Number: D200089821 Product: 80188 EMUL DOS 64765S006 00.01

One-line description:  
Invalid expressions can corrupt PC memory

Problem:  
Detailed Listing for Defect Number LSDqf03471  
Text:

Invalid expressions can corrupt PC memory.

.submitter

If two syntactically incorrect expressions are entered one after the other, PC memory may be corrupted. Data could be corrupted; the interface could hang.

The invalid expressions could be entered in any address or data expression in the PC interface.

resp engr: Harold Shaw

.labnotes

Whenever cefree() is called with a pointer, it frees the space but does not set the pointer to NULL. If a global variable is passed to cefree(), it may free space that has already been freed.

Jeff Downs

.workaround

Be sure that expressions are syntactically correct.

Signed off 07/11/88 in release A01.01

---

Number: D200070060 Product: HP TEAMWORK 300 64711S004 01.00

One-line description:  
Won't open Data Flow Diagram

Problem:  
When working on a DFD, the ERROR MESSAGE:"ERROR: This mode has not been configured for real time objects. your DFD has been opened for READ. see your SA", intermittently occurs... More prevalent when another Pisces II product is running.

Signed off 10/09/87 in release 402.20

Number: D200076505 Product: HP TEAMWORK 300 64711S004 01.00

One-line description:  
I/O timing loops are machine dependent. 350 runs much faster than 320.

Problem:  
Timing loops for items like "waiting for a key entry" are machine dependent. Hence, they usually run much faster on a 350 than a 320. This will make things like "repeat a character" when a key is held down happen much faster.

Temporary solution:  
None at this time.

Signed off 10/09/87 in release A02.20

Number: D200076521 Product: HP TEAMWORK 300 64711S004 01.00

Keywords: CUSTOMIZE

One-line description:  
Should keep the manual pages if /usr/man/man1 doesn't exist.

Problem:  
If one is doing a custom installation where hptwk isn't being installed under /usr/hp64000/...., it is quite possible that the user has removed /usr/man/man\*. If this is the case, the customize script should leave the man' pages alone and not remove them from \$PWD/usr/man/man1 as it presently does.

Signed off 10/09/87 in release A02.20

Number: D200076968 Product: HP TEAMWORK 300 64711S004 01.00

One-line description:  
Title changes do not 'filter down' to lower levels.

Problem:  
Changing the title of a SC in a process index does not change the title in the box in the SC.

Temporary solution:  
None at this time.

Signed off 10/09/87 in release 402.20

Number: D200078717 Product: HP TEAMWORK 300 64711S004 01.00

One-line description:  
FILES MISSING WHEN 64702 IS INSTALLED WITHOUT THE 64711 FILESET

Problem:  
When the 64702 fileset is loaded on a machine without the 64711 fileset, two files required by the 64702 must be copied from a machine that has the 64711 fileset loaded. They are /usr/hp64000/hptwk/twk/install/install.msg

and /usr/hp64000/hptwk/twk/config\_file. These files must be copied to the machine where the 64702 fileset was loaded or the following error messages result:

```
NO_TWK_INSTALL_MSG1_FILE
CANNOT_OPEN_CONFIG_FILE
```

Temporary solution:  
The two files required by the 64702 must be copied from a machine that the 64711 fileset loaded. They are:  
/usr/hp64000/hptwk/twk/install.msg  
and /usr/hp64000/hptwk/twk/config\_file. These files must be copied to the machine where the 64702 fileset was loaded.

Signed off 10/09/87 in release 402.20

Number: 5000196048 Product: HP TEAMWORK 300 64711S004 01.00

One-line description:  
Better use of laser printers.

Problem:  
USING A LASERJET-PLUS TO PRINT RESULTS IN HARDCOPY USING ONLY 1/4 OF A PAGE INSTEAD OF THE WHOLE PAGE. THIS RESULTS IN LARGE DFD'S BEING VERY DIFFICULT TO READ AND HURTS HP'S CLAIM THAT WE HAVE "THE BEST PERIPHERAL SUPPORT". THE HP74200 "EDS" PRODUCT HAS NO PROBLEM WITH FULL PAGE LASER PRINTOUTS.

Temporary solution:  
None.

Signed off 10/23/87 in release 402.20

Number: D200067371 Product: HP TEAMWORK 300 64711S004 01.00

One-line description:  
Need ability to import and export notes to and from HP-UX environment.

Problem:  
Customer would like to be able to create notes using an editor in HP-UX and then import them into HP Teamwork. This option is available in the P-spec body pull-down menu with the "Paste Body from file" menu selection. There should also be a selection "Write Body to File" to export notes into the HP-UX environment.

Signed off 10/09/87 in release 402.20

---

Number: D200076992 Product: HP TEAMWORK 300 64711S004 01.00

One-line description:  
Wrong date displayed by load\_twk.

Problem:  
load\_twk displays all the parameters it was invoked with and  
the date of "Wed Dec 31 16:59:59 1969".

Signed off 10/09/87 in release 402.20

---

Number: D200076687 Product: STATE ANALYZER 300 64620S004 01.10

One-line description:  
State Pv causes cardcage IMB to latch.

Signed off 07/11/88 in release A01.30

---

Number: D200082388 Product: STATE ANALYZER 300 64620S004 01.10

One-line description:  
Processes sometimes left running after parent has stopped.

Problem:  
Sometimes, when the parent process to a measurement system is killed  
some of the measurement systems processes are left running. Please  
change the behaviour of the products so that these processes die  
nicely.

Temporary solution:  
If the tty associated with the process is a pty, then you can  
release the processes by  
cat < ptyxx  
This causes the pending output to be flushed, and the processes will die  
naturally.

Signed off 07/11/88 in release A01.30

---

Number: D200082487 Product: STATE ANALYZER 300 64620S004 01.10

One-line description:  
Display symbol shows "symb not found" when showing sym within process.

Signed off 07/11/88 in release A01.30

---

Number: D200087528 Product: STATE ANALYZER 300 64620S004 01.10

One-line description:  
State does not yet support the system II "set" command

Signed off 07/11/88 in release A01.30

---

SRB detail reports as of 07/11/88

Page: 13

Number: 5000259838 Product: UTILITIES PKG 300 64888S004 01.10

One-line description:

Xlate cannot convert the file with address 0FFFFH

Problem:

Xlate can not convert the file including address 0FFFFH.  
Xlate generates error "xlate: invalid address, address too large for processor".

Example: "tem"  
"8085"

```
ORG 0FFFFH
DB "A"
```

After made absolute file, excuted " xlate -t ih80 -f tem.X ".  
Error occured. The message is discribed above.

Temporary solution:

No temporary solution at this time.

Signed off 07/11/88 in release A01.20

---

Number: 5000185447 Product: UTILITIES PKG 300 64888S004 01.00

Keywords: ENHANCEMENT

One-line description:

Desire ability to control the length of S-Records output from 64888.

Problem:

This SR is submitted against 64888 Transfer Utility Package, but since the product is not loaded in the database yet, I used the 68010 linker part number.

Customers using the 64888 Transfer Utility Package need the capability to control the length of the S-records that are being output from xlate. Motorola standards say that the records may be of any length up to 255 bytes, and the xlate utility will output records that are consistantly 255 bytes if necessary and then fill the last record with the remainder. However some older microprocessor systems were designed with a fixed length S-record scheme. For example the 64100 terminal emulator upload function outputs S-records that are 28 bytes in length including header information, checksum and data. I have a target system that has been designed with this scheme in mind and consequently expects S-records to be of this length. Therefore to accomodate older systems an enhance-ment to the xlate command that allows record length specification would be greatly appreciated.

Signed off 07/11/88 in release A01.20



**5958-6019, August 1988  
E0888**

**Printed in U.S.A.**