




CHANGE NOTICE: 459 (10-26-65)  
EFFECTIVE DATE: OCT. 1965





FIGURE 5-16. SWITCH BLOCK ASSEMBLY, 382B1657.





Läs- och styr vipper  
Del 1

1/3-69  
97

